

CLASSIFIED MESSAGE

TOP SECRET

2122Z 21 JUN 58

ROUTING

1	4
2	5
3	6

DIRECTOR

FROM

FROM: OPS (1,2)

TO: S/C (3)

RHH

4591 (IN 41551) 2122Z 21 JUN 58

ADIC

INFO

OPIM

CITE

21/2100Z

A 6013

B 21/2047Z

C DELAY DUE TO FAULTY SEAT PACK OXYGEN REGULATOR.

END OF MESSAGE

25X1

25X1

25X1

25X1

25X1

OPERATIONAL**IMMEDIATE****OPERATIONAL
IMMEDIATE****TOP SECRET****TOP SECRET**

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy No.